




Magnetic Auto-Release Sweeper Assembly & Operating Instructions

Assembly



1 Twist top portion of handle counter-clockwise & extend. This will pull the wire up into the handle.



3 Turn handle clockwise to lock into position.



4 Press snap-button and insert handle.



5 Snap-button must seat completely into the hole.


Operating




1 Roll over area to be cleaned.



2 When sweeper head is full, position over container where you wish to deposit debris.



3 To release material. Hold lower portion, turn handle counter-clockwise and pull two inches.



4 Allow handle to return two inches towards sweeper head. Lock handle into place by turning clockwise.

METER-MAN, INC.

2 South Main • P.O. Box 746 • Winnebago, MN 56098 U.S.A. • 507-893-4806 • 800-338-5756 • FAX 507-893-3517
www.meter-man.com • e-mail: meterman@bevcomm.net